


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-166	Dye	4/29/2009	ADS/TM	S13AA1014MH	Damp	NA		
Address	Towanda Avenue & Springhill Ave		Location	Paved asphalt	Status	Public	Source	Storm Manhole



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-166	Dye	4/29/2009	ADS/TM	S13AA1014MH	Damp	NA


Address	Towanda Avenue & Springhill Ave	Location	Paved asphalt	Status	Public	Source	Storm Manhole
----------------	---------------------------------	-----------------	---------------	---------------	--------	---------------	---------------

Observations & Photos

Obs_ID D1028-166-OB01

Nearest MH S13AA1002MH

Comments Dye observed 41.9 ft. upstream of S13AA1002MH. Infiltration gusher from service lateral at 9 oclock.



Picture \D1028-166-OB01-P01.jpg

Comments 41.9 ft. upstream of S13AA1002MH along S13AA1014G1 at service lateral.

Obs_ID D1028-166-OB02

Nearest MH S13AA1002MH

Comments Dye observed 100.8 ft. downstream of S13AA1002MH. Infiltration dripper at service lateral at 2 oclock.



Picture \D1028-166-OB02-P01.jpg

Comments 100.8 ft. downstream of S13AA1002MH along S13AA1002G1 at service lateral.